Application/Control Number: 10/016,839 Page 2

Art Unit: 1731

EXAMINER'S AMENDMENT

An examiner's amendment to the record appears below. Should the changes and/or additions be unacceptable to applicant, an amendment may be filed as provided by 37 CFR 1.312. To ensure consideration of such an amendment, it MUST be submitted no later than the payment of the issue fee.

Authorization for this examiner's amendment was given in a telephone interview with Adenike Adewuya on 5/4/04. As indicated in the Interview Summary, it was noted to applicant that claim 6 read on Deeren et al reference. Applicant proposed amending claim 6 to recite that the claimed assembly was not in bundle form but in a layered horizontal form as shown in figure 6A. However, it was noted that applicant's proposal would invoke a 103(a) rejection under Deeren et al in view of Niedorf. Applicant then agreed to revert to the original language of claim 6 and change its dependency to the indicated allowed claim 13.

The application has been amended as follows:

Claim 6 has been rewritten as follows:

6. (currently amended) The A method of claim 13, wherein assembling a plurality of glass rods comprises arranging the glass rods in a row between a mat producing lenses, comprising:

assembling a plurality of glass rods having a desired length in side-by-side configuration into a single unit, wherein assembling a plurality of glass rods comprises arranging the glass rods in a row in between a mat such that the mat is peelable from the glass rods;

Application/Control Number: 10/016,839

Art Unit: 1731

cutting the single unit into multiple slices, each slice comprising an array of glass rod pieces;

finishing the slices to a desired thickness and surface finish; and
extracting the glass rod pieces from the slices to produce a plurality of individual
lenses.

REASONS FOR ALLOWANCE

The following is an examiner's statement of reasons for allowance: The cited prior art fails to disclose or reasonably suggest assembling a plurality of glass rods into a single unit, cutting the single unit into multiple slices, and finishing the slices by forming a facet angle on at least one of the slices. While the prior art (US 4760672) teaches of providing a facet angle on a glass rod, it does not disclose or reasonably suggest providing a facet angle to a slice comprising a plurality of glass rods as recited in the instant claims.

Any comments considered necessary by applicant must be submitted no later than the payment of the issue fee and, to avoid processing delays, should preferably accompany the issue fee. Such submissions should be clearly labeled "Comments on Statement of Reasons for Allowance."

Any inquiry concerning this communication or earlier communications from the examiner should be directed to Carlos Lopez whose telephone number is 571.272.1193. The examiner can normally be reached on Mon.-Fri. 8am - 5pm.

Application/Control Number: 10/016,839

Art Unit: 1731

If attempts to reach the examiner by telephone are unsuccessful, the examiner's supervisor, Steven Griffin can be reached on 571.272.1189. The fax phone number for the organization where this application or proceeding is assigned is 703-872-9306.

Information regarding the status of an application may be obtained from the Patent Application Information Retrieval (PAIR) system. Status information for published applications may be obtained from either Private PAIR or Public PAIR. Status information for unpublished applications is available through Private PAIR only. For more information about the PAIR system, see http://pair-direct.uspto.gov. Should you have questions on access to the Private PAIR system, contact the Electronic Business Center (EBC) at 866-217-9197 (toll-free).

SUPERVISORY PATENT EXAMINER
TECHNOLOGY CENTER 1700

Page 4

CL